



ECHLIN

GDI HIGH-PRESSURE FUEL PUMP KITS

WHAT'S IN YOUR BOX?

The All-in-One High-Pressure Fuel Pump Solution

New, GDI-high pressure fuel pump Kits make it easier to perform a complete service.

What's inside the Echlin® box...
precision manufacturing and
everything needed for a complete
repair. What's in your box?

Echlin® Kits are available for popular
import and domestic applications, and
include the components needed to
optimize GDI fuel pressure:

- High-Pressure Fuel Pump
- Cam Follower
- Mounting Hardware
- Seals



Precision-manufactured kits
include everything required for
a complete service

IMPORT & DOMESTIC

Coverage for popular import and
domestic vehicles

100%

TESTED & VALIDATED

Lab tested and validated on
actual vehicles

Echlin® Solutions

Problem:

Fault codes P0087 (fuel pressure is too low) or P0088 (fuel pressure is too high) can be caused of a failed GDI high-pressure fuel pump OR a failed camshaft follower.



Echlin® Solution:

Installing a new high-pressure pump with a new cam follower helps ensure correct fuel pressure in the GDI system.




Echlin® delivers all-in-one kits



2-34163K

GM Cars and SUVs
(2019-16) VIO: 1.6M



LOOKS RIGHT. FITS RIGHT. PERFORMS RIGHT.

NAPAEchlin.com