



ECHLIN

NEW PARTS SPOTLIGHT

2025

GM Tail Light Wiring Harnesses

NAPA Echlin's all-new complete harness assemblies eliminate the need to cut and splice the original harness when a single socket fails. These components are precision engineered and come completely assembled to make replacement quick, easy and reliable.



GMC Sierra 1500, 2500, 3500
(2015-14) VIO: 550K



LS2519
Left Rear



LS2520
Right Rear



Chevrolet Silverado 1500, 2500, 3500
(2015-14) VIO: 1.3M



LS2521
Left Rear



LS2522
Right Rear



GMC Sierra / Chevrolet Silverado
1500, 2500, 3500
(2019-16) VIO: 2.4M



LS2523
Left Rear



LS2524
Right Rear



For more specific application data, visit NAPAEchlin.com



ECHLIN

LOOKS RIGHT. FITS RIGHT. PERFORMS RIGHT.

NAPAEchlin.com